# Replicant - Issue #2135

## Warn about mutiple similar commands sections

09/23/2020 03:02 PM - Denis 'GNUtoo' Carikli

| | | | | |
|---|---|---|---|---|
| **Status:** | New | | **Start date:** | 09/23/2020 |
| **Priority:** | Normal | | **Due date:** | |
| **Assignee:** | | | **% Done:** | 0% |
| **Category:** | Installation instructions | | **Estimated time:** | 0.00 hour |
| **Target version:** | Replicant 6.0 | | **Spent time:** | 0.00 hour |
| **Resolution:** | | | **Grant:** | |
| **Device:** | Unknown | | **Type of work:** | Wiki editions |
| **Description** | | | | |
| | | | | |

## History

**#1 - 09/23/2020 03:05 PM - Denis 'GNUtoo' Carikli**

As the installation instructions aren't generated yet. I've seen one case where somebody was trying the wrong commands to backup the EFS because that person accidentally scrolled the page without seeing it due to the touchpad not being in a convenient location on that person's laptop.

That could be very dangerous if that happens with the BOOT partition as on some devices this is the bootloader.

In addition if we have u-boot in the kernel partition this will really need to be fixed as u-boot is small enough for heimdall to not refuse to flash it in the bootloader partition, which would break the device (the bootloader is signed so adding u-boot there as-is won't work).

**#2 - 03/29/2021 03:53 PM - Denis 'GNUtoo' Carikli**

*- Type of work Wiki editions added*