

Issues

#	Project	Status	Priority	Target version	Subject	Assignee	Updated	Category	Device	Upstream patch status
1806	Replicant	New	Normal	Any version	modem shell enable/disable script: verify with measurements through a BTS that the modem is disabled		03/23/2021 05:30 PM	Telephony and mobile data		
1791	Replicant	New	Normal	Replicant 6.0	[RepWifiApp] Instable interface wlan0 on i9100		03/23/2021 05:13 PM	Wi-Fi	Galaxy S 2 (I9100)	